

TABLE OF CONTENTS

CHAPTER 1 Introduction and Objectives.....	1
1.1. Introduction.....	1
1.2. Objectives	2
CHAPTER 2 Project Background	3
2.1. Test Road Description.....	3
2.2. Data Collection Overview.....	4
CHAPTER 3 Pavements	7
3.1. Introduction.....	7
3.2. Data Collection	7
3.2.1. NCDOT Survey – Asphalt Concrete Sections	7
3.2.2. NCDOT Survey – Portland Cement Concrete Sections	9
3.2.3. NCDOT Survey – Additional Data Elements	10
3.2.4. LTPP Survey – Asphalt Concrete Sections	10
3.2.5. LTPP Survey – Portland Cement Concrete Sections	10
3.3. Data Analysis	12
3.3.1. NCDOT Survey	12
3.3.2. LTPP Survey	13
3.4. NCDOT Asphalt Concrete Survey.....	14
3.4.1. Fatigue Cracking	14
3.4.2. Transverse Cracking	26
3.4.3. Rutting.....	31
3.4.4. Ride Quality	36
3.4.5. Other Quantities	41
3.4.6. Pavement Condition Rating	43
3.4.7. NCDOT Asphalt Concrete Survey Summary	49
3.5. NCDOT Portland Cement Concrete Survey	50
3.5.1. Patching.....	50
3.5.2. Pumping	53
3.5.3. Surface Wear.....	54
3.5.4. Ride Quality	56
3.5.5. Longitudinal Cracking	59
3.5.6. Transverse Cracking	64
3.5.7. Corner Break.....	69
3.5.8. Spalling	73
3.5.9. Joint Seal Damage.....	77
3.5.10. Data Processing and Results	77
3.5.11. Shoulder Condition	81
3.5.12. Pavement Condition Rating	82
3.5.13. NCDOT Portland Cement Concrete Survey Summary	86
3.6. LTPP Asphalt Concrete Survey	87
3.6.1. Cracking.....	87
3.6.2. Patching and Potholes	97
3.6.3. Surface Deformation.....	98
3.6.4. Surface Defects	100